

**Milly Southworth**

---

**From:** Highways & Environment East <handee@cormacltd.co.uk>  
**Sent:** 20 January 2022 15:07  
**To:** opsman@torpointtowncouncil.gov.uk  
**Cc:** admin@torpointtowncouncil.gov.uk  
**Subject:** RE: Pedestrians being splashed on Trevol Road Torpoint.

Information Classification: CONTROLLED

Dear Philip

Thank you for your email dated 8<sup>th</sup> December.

The areas mentioned appear on the monthly driven strategic route inspection regime. I will ask the Highways Safety Inspector and Highways Steward to pay attention to Woodland Way toward Carbeile School.

Thank you for bringing this to our attention.

Kind regards

**Will Glassup**  
**Highways and Environment Manager**

**Cormac Solutions Ltd**

Tel: 0300 1234 222

Email: [handee@cormacltd.co.uk](mailto:handee@cormacltd.co.uk)

---

**From:** opsman@torpointtowncouncil.gov.uk <opsman@torpointtowncouncil.gov.uk>  
**Sent:** 08 December 2021 12:08  
**To:** Highways & Environment East <handee@cormacltd.co.uk>  
**Subject:** Pedestrians being splashed on Trevol Road Torpoint.

Good Afternoon,

We have received correspondence from a concerned resident, please see extracts from her message below.

*I have an enquiry and was told you may be able to point me in the right direction as to who I can speak to about it. Long story short, every time it rains (literally every time), my daughter and I are splashed by drivers on Trevol Road, who can't be bothered to slow down and have zero regard for pedestrians. I'm talking entirely soaked to the bone drenched with water. It's not fair to my child to have to sit through school in wet clothes because drivers won't slow down ..... I'm hoping I can speak to someone who can look into doing something to help prevent this (signs, a camera, just something to actually get people to slow down and take care during wet weather) as it's quite hard to get a picture or video of the cars in question after the fact as they've usually driven off by that point.*

After speaking to her myself it seems that there are 3 points of concern

- Water pooling at the bottom of the hill between Goad Ave and Woodland Way.
- Insufficient drainage between woodland way and Carbeile School 1<sup>st</sup> Pedestrian entrance by the safety barriers.
- Also between Woodland Way and Carbeile School the trees etc that line the pavement encroach onto the footway meaning that there forced to walk closer to the road.

Please could you look into rectifying any of these issues?

Kind regards  
Phil

**Philip Griffiths**

Operations Manager Torpoint Town Council

**p.** 07949530320

**e.** [opsman@torpointtowncouncil.gov.uk](mailto:opsman@torpointtowncouncil.gov.uk)

**w.** [www.torpointtowncouncil.gov.uk](http://www.torpointtowncouncil.gov.uk)

**a.** 1-3 Buller Road Torpoint Cornwall PL11 2LD



Virus-free. [www.avg.com](http://www.avg.com)

This e-mail and attachments are intended for above named only and may be confidential. If they have come to you in error you must take no action based on them, nor must you copy or show them to anyone; please e-mail us immediately at [customerrelations@cormacltd.co.uk](mailto:customerrelations@cormacltd.co.uk) Please note that this e-mail may be subject to recording and/or monitoring in accordance with the relevant legislation and may need to be disclosed under the Freedom of Information Act 2000 or the Environmental Information Regulations 2004. Security Warning: It is the responsibility of the recipient to ensure that this e-mail and any attachments are virus free. CORMAC will not accept liability for any damage caused by a virus. CORMAC Solutions Ltd - A Cornwall Council Company Registered in England No. 07737430 Registered Office Higher Trenant, Wadebridge, PL27 6TW CORMAC Contracting Ltd - A Cornwall Council Company Registered in England No. 07737521 Registered Office Higher Trenant, Wadebridge, PL27 6TW