







Site Visit Report

Our Ref:

Installation:

Premises:

Signalling:

Order No:

The Whitehouse Callington Road Saltash PL!2 6LL

:TORP :FIRE

A) Fire Alarm System Commercial BS5839

Name

Torpoint Town Council

Address

Council Chambers 1-3 Buller Road

Torpoint

Cornwall

Postcode PL11 2LD

Engineer

Martin Singleton

Called Arrived 31/03/22 16:42 04/04/22 12:25

Left

04/04/22 13:24

Parts + Materials Used:

Optical Smoke XP95

TORPOINT

B) Commercial

EG) Dualcom Digiair

82548

Reason for Visit: CCTV/Lights/Access/Fire System fault

1.00

Job / Docket Ref:

Findings and Action Taken:

Device 22 smoke detector showing duplicate address and call point 18 main hall stage missing.
Checked device 22 smoke detector In cupboard. Found bags jammed against head putting pressure on the smoke head program buttons. Replaced smoke detector one button stuck. Panel clear upon departure

Outstanding company action:

[04/04/22] No descriptors on panel needs uploading from laptop file

There were no disconnections on this visit.

There were no isolations on this visit.